

Date: 5/8/01 Express Mail Label No. EL551548245 US

Inventor: David B. Russell, Walter Henry Zengerle III, Peter Charles Conway, James F. Bredt, Benjamin Daniel Sweet-Block, and Robert Anthony Phillips

Attorney's Docket No.: 2247.1001-007

METHOD AND APPARATUS FOR PROTOTYPING
A THREE-DIMENSIONAL OBJECT

RELATED APPLICATIONS

5 This application is a Continuation-in-Part of U.S. Application Number 09/416,787, filed October 13, 1999, which is a Continuation-in-Part of U.S. Application Number 08/771,009, filed December 20, 1996, the entire teachings of both of which are incorporated herein by reference.

BACKGROUND OF THE INVENTION

10 Rapid prototyping describes various techniques for fabricating a three-dimensional prototype of an object from a computer model of the object. One technique is three-dimensional printing whereby a special printer is used to fabricate the prototype from a plurality of two-dimensional layers. In particular, a digital representation of a 3-D object is stored in a computer memory. Computer software sections the 15 representation of the object into a plurality of distinct 2-D layers. A 3-D printer then fabricates a layer of material for each layer sectioned by the software. Together, the various fabricated layers form the desired prototype.

In one method of three-dimensional printing, layers of a powder material are deposited in a confined area. A binder solution is selectively deposited on each layer to 20 produce regions of bound powder. The unbound powder is then removed to yield a three-dimensional part.

SUMMARY

A system is provided for fabricating a three-dimensional object from a substance, such as a powdered build material. A second material, such as a liquid binder material, can be used to bind the build material at particular locations to form the
5 three-dimensional object.

- In accordance with one aspect of this invention, a three-dimensional printer includes multiple printheads for printing a binder liquid, which can include a binder that has been mixed with a colorant to form a colored binder liquid, onto a bed of build material in a build chamber. The printheads can be mounted on a gantry that is
10 designed for reciprocal displacement across a build chamber along a slow axis. The printheads, in turn, can reciprocally move across the gantry on a fast axis to enable displacement of the printheads along both the fast and slow axes so that the printheads can deposit binder liquid, which can be colored, across the surface of a bed of build material in the build chamber.
15 After each pass of the printheads across the bed along the fast axis, the printheads can be advanced a step along the slow axis and then passed again across the bed along the fast axis. This process can be repeated until an entire layer is printed on the bed of build material. An additional layer of build material can then be deposited via the same process.
20 The printheads can be offset from one another on the gantry in the direction of the slow axis. With this configuration, the printheads can print adjacent or overlapping lines across the bed of build material when the printheads are passed across the bed along the fast axis, thereby printing a broader swath of binder liquid, including colored binder liquid, onto the bed with each pass of the printheads across the bed. Each of the
25 printheads can print binder liquid alone or binder liquid mixed with colorant.

The system for fabricating a three-dimensional object can be used to form colored objects. Further, multiple printheads can be used to print binder liquid onto the build material.

In accordance with another aspect, the printheads can respectively be coupled with multiple external binder sources. For example, each of at least three printheads can be coupled with a different colorant having one of the three primary colors (cyan, yellow, and magenta) or black. An external binder-liquid source can also be coupled

5 with each of the printheads and at least one additional printhead can be provided to print binder liquid. The binder liquid supplied by the binder source can be colorless (that is, clear or white). The binder-liquid source and colorant sources can further be configured either to mix the binder liquid and colorants before printing or to alternatively deliver either binder liquid or colorant to the printheads. Further still, the printheads can be

10 aligned in at least two rows, the rows being displaced from one another along the slow axis. Within each row a color printhead (coupled with a colorant source) can be paired with a colorless printhead (coupled with a colorless binder-liquid source).

In accordance with yet another aspect, the conduits connecting the external binder liquid sources to the printheads can include return loops that allow unwanted

15 binder liquid and entrapped air to be easily purged from the system.

The printing process can be governed by software instructions stored on a computer-readable memory coupled with a processor, the processor also being coupled with the printheads. The software can include instructions for tapering bands of colored binder liquid printed at an edge of the printed object to leave a section between adjacent

20 bands uncolored to thereby reduce the mixing of colors at edges of the object where bands of different colors meet. The software can further include instructions for printing a higher concentration of colorant at the tapered segments of the bands to thereby provide consistency in color intensity across the surface of the object notwithstanding the thinning of the depth of colorant printing at the edges.

25 A system for fabricating a colored three-dimensional object is provided that uses a clear binder liquid and a colored binder liquid at a particular location of the object. It is desirable to deposit a predetermined amount of total binder liquid at the particular location to bind the material without over saturating the build material with binder liquid.

A particular system deposits a binder liquid on build material at a particular location in a three-dimensional printer. The system can include determining the total amount of binder liquid needed to solidify the build material at the particular location, determining the amount of each of the colored binder liquids needed to produce the

5 desired color at the particular location and determining the amount of colorless binder liquid that needs to be added to the colored binder liquids to obtain the predetermined total binder liquid requirement. The sum of all the binder liquid amounts to be applied, both colored and colorless, is thereby made to approximately equal a sufficient amount of total binder liquid needed to solidify the build material at the particular location of

10 build material.

A system for drawing or pushing air through a three-dimensional printer is provided for purposes such as holding the object being formed during fabrication to improve the quality of the object.

A further apparatus for fabricating a three-dimensional object includes a feed

15 reservoir having stored therein a supply of build material for forming the object, a build chamber for receiving incremental layers of the build material from the feed reservoir, and a vacuum pump coupled to the feed reservoir and/or to the build chamber to create an airflow through the feed reservoir and/or the build chamber.

A system for cleaning the printheads is also provided. A particular apparatus for

20 fabricating a three-dimensional object can include a structural frame, a build chamber which is supported by the frame and that can be filled with a build material, a gantry mounted for displacement across the build chamber, at least one printhead mounted on the gantry, and at least one cleaning element movable relative to the frame for cleaning the at least one printhead.

25 A system for reclaiming unused build material is provided such that the build material can be used again thereby eliminating waste. In one embodiment, an apparatus for fabricating a three-dimensional object can include a frame, a build chamber mounted to the frame and suited for being filled with a build material, a chute defining an overflow cavity, the chute being positioned to receive overflow build material from the

build chamber, and a removable collection chamber coupled with the chute to receive build material that passes through the chute.

The above and other features including various novel details of construction and combination of parts, will be more particularly described with reference to the
5 accompanying drawings and pointed out in the claims. It will be understood that the particular method and apparatus for prototyping a three-dimensional object embodying the invention is shown by illustration only and not as a limitation of the invention. The principal and features of this invention may be embodied in varied and numerous embodiments without departing from the scope of the invention.

10 10 BRIEF DESCRIPTION OF THE DRAWINGS

FIG. 1 is a schematic of an apparatus for rapid prototyping.

FIG. 2 is a top side view of an embodiment of the three-dimensional printer of FIG. 1.

15 FIG. 3A is a perspective view of the basic elements for regulating and utilizing airflow through an embodiment of the three-dimensional printer of FIG. 1.

FIG. 3B is a view illustrating the use of a system for reclaiming spent build material.

FIG. 3C is a perspective view of a plenum for use with the three-dimensional printer of FIG. 1.

20 FIG. 3D is a schematic for controlling the airflow through the feed chamber and build chamber of the printer of FIG. 1.

FIG. 4A is a perspective view of an embodiment of a three-dimensional printer of FIG. 1.

FIG. 4B is a perspective view of the gantry of the printer of FIG. 4A.

25 FIG. 4C is a perspective view of the carriage of FIGS. 4A and 4B with its cover open.

FIG. 4D is a perspective view of a cleaning assembly used to clean the print jets.

FIG. 4E is a partial perspective view illustrating the internal components of the

cleaning assembly shown in FIG. 4D.

FIGS. 5A-5D are schematics of a process for controlling print medium.

FIG. 6 is a schematic of an apparatus employing multiple printheads.

FIG. 7 is a schematic of a printhead having a faulty binder jet.

5 FIG. 8 is a schematic of a method of printing two layers with a faulty binder jet.

FIG. 9 is a partially cut-away view of an object that has been formed from at least two different colors.

10 FIG. 10 is a partially cut-away view showing a method of controlling appearance where differing colors meet.

10 FIG. 11A is a schematic block diagram of a pressure-controlled binder liquid supply system.

FIG. 11B is a detail of FIG 11A showing the clear binder liquid portion.

FIG. 11C is a detail of FIG 11A showing the colored binder liquid portion.

DETAILED DESCRIPTION

15 FIG. 1 is a schematic of a particular apparatus for rapid prototyping. As illustrated, there is a computer 1, a three-dimensional printer 3, a formed 3-D printer object 5, a post-processing system 7, and a post-processed 3-D prototype object 9.

The computer 1 can be a personal computer, such as a desktop computer or a portable computer. The computer 1 can be a stand-alone computer or a part of a Local 20 Area Network (LAN) or a Wide Area Network (WAN), including public access communication networks such as the Internet. In accordance with the invention, the computer 1 includes a software application 12, such as a Computer Aided Design (CAD)/Computer Aided Manufacturing (CAM) program. The CAD/CAM program 12 manipulates digital representations of three-dimensional objects 17 stored in a data 25 storage area 15. The CAD/CAM program 12 can create, modify and retrieve the stored representations 17. When a user desires to fabricate a prototype object 9 of the stored object representation 17, the user exports the stored representation to a high-level software program 18. From the high-level program 18, the user then instructs the

program 18 to print. The program 18 sections the digital representation 17 into a plurality of discrete two-dimensional layers, each of a predetermined thickness.

The program 18 prints each layer by sending high-level instructions to control electronics 52 in the printer 3, which operates the three-dimensional printer 3.

- 5 Alternatively, the digital representation of the object 17 can be directly read from a computer-readable medium (e.g., magnetic or optical disk) by printer hardware. The three-dimensional printer 3 includes a dirty area 20 where the printing is performed and a clean area 50 where control electronics 52 are housed.

The three-dimensional printer 3 uses inkjet type printheads to deposit binder
10 onto successive layers of a powdered build material, such as disclosed in U.S. Patent No. 5,902,441 to Bredt, et al., the teachings of which are incorporated herein by reference in their entirety. Where the binder combines with the build powder, the powder reacts and cures into a solid structure. By controlling the placement of binder droplets from these printheads, the solid structure of the 2-D cross section can be
15 physically reproduced. The three-dimensional printer 3 fabricates a physical layer for each sectioned layer provided by the program 18. When the file has been completely printed, a three-dimensional part 5 has been formed. Further details of binding a powder to form an object are disclosed in U.S. Patent Nos. 5,340,656 to Sachs et al., 5,387,380 to Cima et al., and U.S. Application No. _____ entitled Compositions for
20 Three-Dimensional Printing of Solid Objects, filed on April 13, 2001, by Bredt et al. (Attorney Docket No. 2247.2001-001), the teachings of which are incorporated herein by reference in their entirety.

The post-processing system 7 may be used to improve the prototype object 9 from the printed part 5. Various finishing options are available depending on the result
25 to be achieved.

Those of ordinary skill in the art should recognize that methods involved in prototyping a three-dimensional object may be embodied in a computer program product that includes a computer usable medium. For example, such a computer usable medium can include a readable memory device, such as a solid state memory device, a

hard drive device, a CD-ROM, a DVD-ROM, or a computer diskette, having computer readable program code segments stored thereon. The computer readable medium can also include a communications or transmission medium, such as a bus or a communications link, either optical, wired, or wireless, having program code segments
5 carried thereon as digital or analog data signals.

FIG. 2 is a top schematic view of an embodiment of the three-dimensional printer 3 of FIG. 1. Shown in more detail are the front powdery area 20 and the rear clean area 50. The top deck 22, in addition to the three apertures for chambers 24, 26, 28 includes an abrasive section 29 discussed below. A print gantry 40 is suspended
10 over the top deck 22 by an arm assembly 55 connected to a track 57 and a support rod 23. During operation, the arm moves along the x-axis (slow axis) on the track 57 and the support rod 23 to move the gantry 40.

As illustrated, the gantry 40 carries a printhead 45, which deposits binder liquid. The printhead 45 reciprocates in the y-axis direction along a print track 46. The gantry
15 40, in one embodiment, includes at least one ink jet printhead 45, having a plurality of binder jets 47 for depositing a binder liquid. The binder jets receive binder solution from a binder conduit 77. Also illustrated is a spreader roller 48 for dispersing build powder from the feed chamber 24 to the build chamber 26.

20

AIRFLOW

Air can be circulated inside the machine to solve a variety of problems. One specific problem is airborne powder, which can contaminate printer mechanical and electronic components and thereby decrease machine reliability. Also, the powder can accumulate inside the top cover of the machine, thereby reducing the operator's ability
25 to monitor machine operation.

FIG. 3A is a perspective view of the basic elements for regulating airflow through an embodiment of the three-dimensional printer 3 of FIG. 1. As illustrated, the three-dimensional printer 3 includes a top deck 22 having a plurality of apertures. The top deck 22 is mounted to a structural frame. Illustrated along the x-axis (slow axis) are

a rectangular feed chamber 24 having a feed piston 25, a rectangular build chamber 26 having a build piston defining a build table 27, and an overflow chute 28. Although omitted from the drawing for clarity, seals are fixed to the pistons 25, 27 to slide against the walls of the chambers 24, 26. Although also not illustrated, a top cover isolates the
5 printing area from the outside environment.

FIG. 3A also illustrates elements of a printer designed to facilitate reclaiming spent build material. In this printer, build material that flows into the overflow chute 28 is drawn into a collection bucket 81. The collection bucket 81 slides into a mount 82 on the floor of the printer such that the bucket 81 is positioned to receive build material
10 exiting the bottom of chute 28. A top plate 83 forms a seal over the bucket 81, and a blower 34, mounted on top plate 83, creates a downward draft through the chute 28. A filter 31 is mounted on top plate 83 between the blower 34 and the cavity enclosed by the bucket 81 and the top plate 83. Due to the respective positioning of these elements, overflow build material is collected primarily in the bucket 81 rather than upon the filter
15 31.

The build material that falls to the floor of the bucket 81 is more removed from the flow path of the air passing from the chute 28 through the blower 34. The bucket 81 can be easily removed to return the build material back to the feed chamber as illustrated in FIG. 3B. A lip 84 on the bucket 81 further facilitates pouring.

20 In one embodiment, one or more optical sensors are positioned to sense when the bucket 81 is full. For example, optical sensors can be positioned to sense at a location inside of the bottom end of chute 28. When a "full" reading is made, the bucket 81 is removed and the build material is poured back into the feed chamber, including pouring through a screen to remove any contaminants or clumped material.

25 In addition to capturing excess powder, the airflow through the overflow chute 28 reduces the amount of airborne powder to enhance machine reliability and user satisfaction.

In alternative embodiments, a vacuum pump can be connected to the feed chamber 24 and/or the build chamber 26 via conduits. It has been found that drawing

air from the build material in through the bottom of the feed chamber 24, while the chamber is being filled, causes the build material to pack densely and uniformly in the feed chamber. This greatly reduces the need for the operator to work the air out of the build material with a trowel during filling, a time consuming process that tends to
5 produce an undesirable cloud of airborne powder.

It has also been found that drawing air from the build material through the bottom or sides of the build chamber 26 causes the build material to pack more densely in the build chamber. This denser material provides better support for the part being formed in the build chamber. This helps to prevent the part from moving or shifting
10 during the build process, thereby improving the quality of the part being formed.

FIG. 3C illustrates one embodiment of a plenum 240 positionable on the bottom of the feed chamber 24 and build chamber 26. The plenum 240 includes a piston plate 242, which serves as a base for the plenum. A vacuum pump is attached through a port 244.

15 Above the piston plate 242 is a top plate 246 that provides support for a filter medium 248 and is perforated with holes 250. The filter medium 248 maintains a separation between the build material and the vacuum system, which can further include additional in-line filters. The holes 250 provide passage for downward airflow and can be arranged for optimum airflow characteristics.

20 In addition, a plurality of spacers 252 are provided between the piston plate 242 and plate 246 to establish a space for ensuring an even distribution of vacuum in the plenum 240. In addition, gasket 254 between the piston plate 242 and plate 246 inhibits air leakage around the edges of the plenum 240. A mesh 256 is provided above the filter 248 to protect it during setup and cleanup operations. The plenum 240 is
25 sandwiched together with screws along the perimeter that extends from the mesh 256 to the piston plate 242. A seal can be provided on the perimeter of the plenum 256 to prevent powder loss between the piston and the chamber wall.

FIG. 3D is a schematic for controlling the airflow through the feed chamber 24 and/or build chamber 26. As shown, a vacuum pump 258 is coupled to the feed

chamber plenum 241 and build chamber plenum 243 for creating an airflow through either or both plenums. In one embodiment, vacuum pump 258 is capable of pulling a vacuum level of about 10 inches of mercury with a flow rate of 1½ to 2 in³ of air per minute. A first valve 260 is shown disposed between the vacuum pump 258 and the feed plenum 241 and build chamber plenum 243. The first valve 260 allows selective directioning of the airflow through either the feed plenum or the build plenum. In particular, a switch 262 is configured to be activated by the user, for example, to direct the valve 260 such that all the airflow is directed through the feed plenum 242 while the user is filling the feed chamber 24. After the feed chamber 24 is filled, the user can activate the switch 262, which can be a foot pedal, to direct all the airflow through the build plenum 243. A flow meter 261 can be disposed between the valve 260 and/or vacuum pump 258 to measure the air volume flow rate between this valve 260 and the vacuum pump.

A valve 264, which can be a three-way valve, can be further provided between the valve 260 and the build chamber plenum 243. The valve 264 is coupled to and controlled by software instructions 265. More particularly, the software instructions 265 control the valve 264 to selectively allow airflow through the build chamber plenum 243 during the fabrication process by controlling a solid state relay 266 to make contact between power lines 268. For example, airflow can be allowed through the build chamber plenum 243 during application of the build material but turned off during printing of the liquid binder material. In-line gauges 270 can be provided adjacent to the feed and/or build plenums to measure the level of vacuum at these locations. In-line filters 272 can be further provided to filter any build material or debris that may pass through or around plenums 241 and 243. In one embodiment, an adjustable regulator 274 can be provided between the build chamber plenum 243 and the valve 264 for controlling the flow of air through the build chamber plenum 243. A gauge 276 can be further coupled to the regulator 274 for measuring the level of vacuum through the regulator.

PRINTING

Elements of a three-dimensional printer that is particularly suited for high-speed printing in both mono-color and multi-color modes are illustrated in FIG. 4A. A carriage 85 is mounted for reciprocation on the gantry 40. The carriage 85 can 5 reciprocate along the y-axis (fast axis) via a rail 86. The carriage 85, with its cover closed, and the gantry 40 are illustrated with the binder conduits 87 in FIG. 4B. The carriage 85 with its cover open is illustrated in FIG. 4C.

Four substantially-identical printheads 45 (such as Hewlett Packard Part No. C4800A) are mounted within the carriage 85. Each of the printheads 45 are coupled 10 with one of the conduits 87, which in turn are coupled with external binder liquid sources. In one embodiment, one printhead is coupled with a source providing a binder liquid including cyan colorant; a second printhead is coupled with a source providing a binder liquid including magenta colorant; a third printhead is coupled with a source providing a binder liquid including yellow colorant; and the fourth printhead is coupled 15 with a source providing a clear (or white) binder liquid. A fifth printhead coupled with a source supplying a binder liquid including black colorant and offset from the other printheads along the x-axis can further be provided within the carriage 85. The various colorants can be pre-mixed with binder liquid and stored in respective fluid sources, or the colorants can be separately stored and mixed with binder liquid in the machine, for 20 example, at the printhead before printing.

FIGS. 5A-5D are schematics illustrating a process for handling the build powder. Illustrated are the feed chamber 24, the build chamber 26 and the overflow chute 28 depressed in the top deck 22. A supply of build powder 60 is supported in the feed chamber 24 by the movable feed piston 25, and the build table 27 is shown within 25 the build chamber 26. As known in the art, the feed piston 25 moves incrementally upward (in the z+ direction) during operation, while the build table 27 moves incrementally downward (in the z- direction). An airflow down through the overflow chute 28 is created by the blower 34 (FIG. 3A).

Referring to FIG. 5A, the floor 25 of the feed reservoir chamber 24 has been positioned such that a sufficient quantity 62 of build material 60 for one build layer protrudes above the feed chamber 24 . The build table 27 has been positioned to a specific depth to receive a first layer of build material. In one embodiment, the build
5 table 27 is incrementally lowered to create a plurality of successive build layers, each about 3-9 mils thick.

Referring to FIG. 5B, the roller is rotated counter to its forward motion to push the quantity of build material 62 forward toward the build chamber 26. As illustrated in FIG. 5C, the roller 48 continues across the build chamber 26 to deposit a finite layer of
10 build material 64 onto the build table 27. To assure that a full build layer is deposited on the build table 27, an excess amount of build material 60 is provided by and removed from the feed reservoir 24. This excess build material 66 is dumped by the roller 48 into the overflow chute 28 where gravity and air flow carry the particles to the collection bucket 81 (FIG. 3A).

15 Referring again to FIG. 2, as the gantry 40 passes over the top deck 22, a crusted layer is typically generated on the bottom of the gantry as a result of airborne powder mixing with airborne binder material at the gantry surface. This layer tends to become thick over time and drag on the powder bed, causing indentations or grooves on the top layer of the powder bed and leading to flaws in the final part. Small brushes, loop
20 material (e.g., Velcro® fastener material), or another abrasive 29 can be placed on the top deck 22 to scrape excess debris from the bottom of the gantry. This debris may be drawn down into the overflow chute 28.

Having laid a current layer with movement of the gantry in the x-direction, the 2-
D cross-section of that layer is printed. In particular, the printing occurs during
25 successive passes of the printhead in the y-direction during a pass of the gantry in the negative x-direction. Other printing methods can be used instead, as described in detail below.

As the build material is being spread, a wave of powder 65 results and tends to move laterally relative to the roller's direction of motion. The plows 49 tend to contain

the wave of powder 65. This prevents build material from spilling over onto the top deck 22 and forming a ridge, which is undesirable from the standpoint of machine reliability and user satisfaction. The plows 49 form a seal against the ends of rotating and translating spreader roller 48 and against the top of the top deck 22. Springs can be
5 utilized to generate an inward force on the plows 49 toward each other, causing the plows 49 to form a tight seal with the spreader roller 48. Springs also generate a downward force on the plows 49 to form a seal with the top of the top deck 22.

The plows 49 can be fabricated from an oil-filled plastic material to reduce the friction between the bottom of the plows 49 and the top of the top deck 22 during
10 powder spreading. The oil-filled material also forms a barrier which prevents powder from sticking to the bottom of the plows 49. In addition, the oil-filled material may also provide a self-replenishing release layer on the bearing surface of top deck 22.

As the spread roller 48 pushes the wave of powder 65, there is an accumulation of powder on the leading edge, which gets pushed sideways onto the area in front of the
15 plows 49. This powder is pushed along by the plows 49 until it is finally drawn or dropped into the overflow chute 28 or piled out of the way. The overflow chute 28 can be wider than the feed reservoir 24 and build chamber 26 openings to capture this excess powder.

The impact of the binder hitting the powder layer during printing causes powder
20 to fly up and hit the bottom of the printhead. Because the printhead may be wet with binder, the powder may then harden and form a crust on the bottom of the printhead, or it could possibly eventually get inside the jets, thereby clogging the outlet of the jets. In addition, excess binder may occasionally form droplets that rest on the bottom of the
25 printhead and remain there as a result of surface tension. This effect can also cause blocking of the outlet of the jets or deflection of the jets. When jets are blocked or deflected, the binder is not deposited where desired, thereby causing faults in the final part. Therefore, a method is desired to clean the powder or binder from the bottom of the printhead to keep the jet outlets open.

As shown in FIG. 4A, a depression 90 is formed in the top deck 22 which includes at least one squeegee or wiper element movable with respect to the structural frame and top deck 22 for cleaning the print jets. This depression 90 can be formed anywhere on the deck such that the squeegee(s) will be in the path of the print jets.

5 In the embodiment of FIG. 4A, the depression 90 is formed away from the overflow chute 28 opposite the build feed reservoir 24 and build chamber 26. As further illustrated in FIGS. 4D and 4E, a cleaning assembly 200, which is mounted within the depression 90, includes squeegees 209 mounted on a support element 204, which moves up or down by motor 206. More specifically, a motor 206 rotates a gear 208, which intermeshes with
10 and drives a gear 210. The gears 208, 210 are connected to and rotate shafts 212 (only one shaft shown in FIG. 4E), which rotate cams 214 to raise and lower an intermediate element 216, which is attached to a support element 204. A PC board 220 supports sensors 222, which sense the position of squeegees (up or down) by sensing the position of a wheel 224 attached to one of the shafts 212. The wheel 224 includes embedded
15 magnets that are sensed by the sensors 222 to determine whether the squeegees are up or down. The cleaning assembly 200 can include a flange 218 for securing the assembly within the depression 90.

In operation, as the gantry 40 moves past the overflow chute 28 and toward the depression 90, the motor 206 raises the support element 204 upward such that the
20 squeegees 209 extend above the deck 22 to scrape against and clean the printhead faces. The squeegees 209 are then retracted into the depression 90.

In another embodiment, the cleaning squeegee can be fixed in place, such as on the top deck 22. The cleaning squeegee can then be positioned so that the printhead periodically passes over the squeegee, such as every printing pass. Accumulated
25 powder and binder can then be scraped off the printhead by the squeegee. The squeegee can then be cleaned by a cleaning agent from, for example, a proximally-located cleaning jet or from the printhead jets itself. Suitable drainage solutions can also be incorporated into the printer to carry away the waste material. Although a fixed squeegee is less mechanically complex, it may not be suitable for all embodiments.

Although more complex, an advantage of retractable squeegees is that they are protected in the depression 90 when not in use. Also, when the squeegees 209 are positioned below the deck 22 or are moving downward, a nozzle or nozzles 226 containing a cleaning agent, for example, clear binder, can be directed at the squeegees
5 for cleaning the same. With the nozzles 226 positioned below the deck 22, the spray of the cleaning agent is relatively contained within the cavity 90.

In alternative embodiments, the cleaning agent can include a fluid that has lubricating characteristics. That is, the cleaning agent deposits a film on the squeegees 209 that is transferred to the print jets such that the build material is less inclined to
10 stick to the print jets. In a particular embodiment, the cleaning agent includes water mixed with about 5-20% polyethylene glycol.

A support element 204 also carries printhead cap assemblies 202 that can be used to protect the printheads when they are not in use.

PRINT SPEED AND PART QUALITY

15 Maximizing build speed is of great interest to the user. The build time has two primary components: the spreading of the powder and the depositing of the binder liquid. The rate of spreading powder is limited by several factors, including the need to maintain a smooth top layer and to minimize airborne powder. Therefore, one method of increasing the build rate is to increase the rate of binder deposition. A method to
20 increase the speed of depositing binder includes using multiple printheads.

FIG. 6 is a schematic of an apparatus employing multiple printheads. This arrangement maximizes print speed in monochrome print mode because all printheads 45 can print simultaneously, thereby completely covering a total width W_t in the x direction equal to the width of each jet array W_j multiplied by the number of printheads.
25 After printing this total width W_t through the entire y direction, the gantry then advances by a distance equal to the total width W_t in the x-direction. Then the printheads 45 print again covering the total width W_t through the entire y direction again.

This arrangement is also efficient for color printing. In the particular case shown in FIG. 6, there are four printheads 45; each of three printheads prints a primary color and one prints clear. In the case of color printing, the gantry advances by just the width of one jet array W_j , so that each printhead, with its unique color, has the opportunity to 5 pass over each region of the powder.

The reason that the printheads 45 are not placed directly next to each other is that the width of each printhead W_p is greater than the width of the jet array W_j , so if they were placed next to each other there would be a vertical stripe that would not be printed. Therefore, in order to be able to print on every region, the printheads 45 are 10 offset in the y axis by an offset distance W_y to accommodate the physical constraints of the printheads 45.

The printheads 45 are also offset by an offset W_x along the x-axis. In fact, the printheads 45 are aligned such that there is a small overlap W_o of printing coverage in the x axis; that is, two adjacent printheads 45 could print on the same x position 15 simultaneously. This allows for less accuracy during the design and manufacturing process because the printheads 45 can be calibrated after the machine is assembled. Then one of the overlapping printheads 45 can be instructed not to print the few pixels that overlap with those of the another printhead.

Also shown in FIG. 6 are the cleaning elements 209. The cleaning elements are 20 aligned along the y-axis, and spaced so that each cleaning element registers with a respective printhead.

It should be recognized that other multiple printhead configurations can be employed. Detailed descriptions of other exemplary embodiments are disclosed in the incorporated U.S. Application No. 09/416,787. The choice of configurations is a design 25 consideration taking into account various parameters including the printhead specifications.

For example, the printheads 45 can be arranged in a row along the fast y-axis to form a continuous sequence of binder jets. Such an arrangement would not require movement or reciprocation of the printheads 45 along the fast y-axis during binder

deposition.

A variation of this arrangement can include a partial row of printheads along the fast y-axis. Binder deposition would first occur during passage of the printheads along the slow x-axis (in the x^+ direction). Once that pass is complete, the printheads can be
5 indexed along the fast y-axis and binder deposited on the return pass (in the x^- direction). This process can be repeated until full coverage is achieved.

It is also desired to achieve consistently high part strength despite various problems with the operation of particular jets. For example, occasionally certain jets in the printhead may not be firing or the firing may be flickered as a result of a head that is
10 manufactured poorly or one that has become contaminated by powder.

FIG. 7 is a schematic of a printhead having a faulty binder jet. As illustrated, the printhead 45f is one of a plurality of printheads which print along the y-axis as the gantry 40 (FIG. 2) moves. If a particular jet 47-6 of a printhead 45f does not fire, then a stripe 96 may appear in the y direction on the particular layer of powder that is being
15 printed 64. This creates an undesired discontinuity in the printed area 95. The problem is that this vertical strip of unbound powder 96 is at the same x location, x_f , on each layer, thereby causing a plane of delamination once the part is complete.

FIG. 8 is a schematic of a method of printing two layers with a faulty binder jet. In accordance with the invention, a shingling technique is used to cause the unbound
20 vertical stripes 96-1, 96-2 to be placed in different x locations on each layer 64-1, 64-2, thereby distributing the areas of weakness throughout the entire part, instead of concentrating them into one plane. Therefore, the faulty jet 47-6 is located at a different x location on each pass relative to every adjacent layer. Shingling with a multiple cartridge system can be accomplished by a slight offset x_o of the cartridge 45 along the
25 x-axis prior to laying each new layer of binder.

It is also desirable to optimize the part strength while maintaining a high build rate. By depositing more binder per unit area, part strength can be improved. However, high binder volume deposition has the disadvantages of decreasing the build rate and resulting in part distortion. One method to improve the part strength and minimize part

distortion without a large increase in build rate is to increase the volume of binder as it is applied on the perimeter of each layer, thereby forming a hard shell around the part. This can be achieved by increasing the flow rate when the binder is being applied to the perimeter, by applying the binder twice to the perimeter of the part, or by adjusting the
5 binder saturation. This method has the added advantage that it can control distortion of the parts' interior regions.

- To optimize the properties of the model, the amount of binder applied per unit area can be adjusted to match both the specific powder type being used and the geometry of the model. Nominally (saturation = 1), the printhead applies approximately
10 10-20% by volume of binder solution when printing a solid area. The binder volume per unit area can be reduced below this level (saturation <1) while maintaining the same area scan rate by omitting some portion of the pixels printed. To print at a higher than nominal binder volume per unit area (saturation >1), the area scan rate can be reduced while maintaining the same flow from the printhead. This can be accomplished by
15 scaling up the bitmap image in the fast scan direction while simultaneously slowing down the fast axis motor proportionately. To obtain a saturation of 1.5, for example, a 180 x 180 pixel area would be scaled up to 180 x 270 pixels, and the fast axis velocity would be reduced from 90 cm/sec to 60 cm/sec. Through such a variable saturation technique, the strength of the part can be optimized.
20 For example, a part can be formed having a strong shell and a truss or an eggcrate structure in the parts' interior region. The remainder of the interior can remain as loose powder.

COLOR PRINTING

- Color ink jet printheads can be incorporated in the printer, thereby providing the
25 capability of printing a wide range of colors or ink. Because the system uses these heads to deposit liquid binder, they can be used to deposit a color binder as the material that causes the porous material to bind. In particular, the powder material is white or colorless and can absorb the ink to color the powder. As a result, an embodiment of the

invention can build three-dimensional parts that are essentially full color, the color varying throughout the part.

For example, a product designer can produce models of products with various color schemes, labels and decorations already applied to the surface. In addition, a 5 surgeon can prepare for an operation by dissecting a 3-D color-printed model of a patient's body part to become familiar with the three-dimensional arrangement of organs, tumors, blood vessels, etc. Data for the model can be obtained from a Computed Tomography (CT) or Magnetic Resonance Imaging (MRI) scan.

Although some parts may require colored interior regions, other parts may only 10 need surface coloring. Because the visible surface may be the only portion of a part that needs coloring, software can adjust the color ink for use only on the outer edges of each layer. In such a case, a colorless (i.e., clear or white) or mono-colored binder (i.e., a single color other than white) is used on the inside of part, which is not visible to the user. This conserves color binder, which can be more expensive and more cumbersome 15 for the user to obtain for refill.

A certain quantity of liquid binder can be deposited into a given volume of powder to produce a well-formed part. Too much binder can result in the binder migrating beyond the intended area of the part. This effect is customarily called "bleeding." Quantities of binder below this certain amount, however, produce 20 progressively weaker parts. It is desirable to use a sufficiently optimal quantity of binder independent of amount of color. One method for producing parts with controlled variations in color is as follows.

First, a minimum amount of saturation is determined for printing on the edges of each layer (which are, in the end, the surface of the part). Adequate colorant is added to 25 each colored binder such that at this minimum saturation of printing the surface of the final part will be the pure primary color. There are three printheads that print binder colored with each of the three primary colors. There is a fourth head that prints clear binder.

Before printing each layer, the computer software performs an algorithm that

first calculates the amount of colored binder that needs to be printed in each spot by each printhead in order to achieve the desired color. Then the software performs an algorithm which determines the optimum saturation (e.g., increased saturation on the perimeter of each layer, with a truss structure on the interior, as discussed above) for 5 each spot. The software then subtracts the total amount of binder that was already printed by all three color printheads, and then the remaining amount of binder, which is clear and therefore has no impact on the color, is applied by the fourth printhead. Thus each spot receives the correct amount of each color and the correct amount of binder.

To give a background on dithering and halftoning, it is useful to understand it 10 first in monochrome mode. The printer prints onto white powder and could have two sets of jet arrays. One set of jet arrays deposits a black binder, the other set of jet arrays deposits a clear binder which appears white, since the powder is white. At each location in the part being built, the two types of binder are deposited in a ratio to produce the shade of gray, white, or black desired in that region of part. All regions of the part thus 15 receive a sufficient total amount of binder needed to produce a strong part. Such a technique, however, implies printheads that can produce controlled size droplets.

Although an ink jet printhead could be chosen to produce droplets of a 20 controlled range of sizes, most current printheads work best if they are used to produce droplets of one size only. Thus, if the droplets are distributed uniformly across the layer, each location of the part's cross section is hit by either a black droplet or a clear droplet. For dithering or halftoning, these droplets can be distributed in such a manner that when viewed from a sufficient distance a gray is perceived, but when magnified, it is seen as a pattern of dots.

Traditional methods of dithering or halftoning can be used on each layer to 25 determine where to place the droplets of each binder. Algorithms also exist for dithering or halftoning techniques to determine the optimal placement of droplets that fall on what will be the surface of the finished part.

By adding additional nozzles that deposit other colors of binder, the above schemes can be extended to produce full-color parts. Where different-colored surfaces

- in the printed object interface, an algorithm must be applied to the printed area that forms the color band on the perimeter of each layer (see FIG. 9). The simplest algorithm is a simple miter. It should be noted that the parts are not completely opaque, therefore the color that is perceived by the viewer of a part is dependent on the depth
- 5 into the surface of the part into which the color is printed. Therefore, a wide color band will produce stronger colors than a narrower color band.

The problem with any coloring scheme for the color band inside a part where two surfaces of different colors interface is that inevitably at least one color will be printed to less depth into the surface of the part. Therefore, the color will be less

10 concentrated to the viewer of the part. To restore the color to the same level as the colored area with standard depth, greater concentrations of colorant can be printed at the edges of the object's surface.

Because the parts are somewhat translucent, the color of the band relating to one surface can impact the perceived color from an adjacent surface. For example, in FIG.

15 9, if Color 2 is black and Color 1 is white, then the viewer may see the black through the surface that was supposed to be white. To minimize this effect, the respective color bands at adjacent surfaces can be beveled to leave a white or un-colored strip extending from an edge of the object into the object.

For example, with reference to FIG. 10, a band 92 of a first color meets a band

20 94 of a second color at a corner. Tapered area 96 is formed of a clear binder such that bands 92, 94 are perceived as their true color and the perception of each color is impacted less by the presence of the other color in the "background."

A problem arises when the quantity of colored binder needed to produce a well-colored part is greater than that needed to produce a well-formed part. In that case a

25 compromise must be made, either in the accuracy of coloring or in the amount of allowed bleeding. If the pigmented liquids do not function as a binder, it is possible to deposit much larger quantities without affecting mechanical properties of the part.

BINDER SUPPLY

FIG. 11A is a schematic block diagram of a system of printheads 145A-145D fed by pressure-controlled conduits 87A-145D. As shown, the binder supply system includes a plurality of printheads 145A, 145B, 145C, 145D coupled to a plurality of binder supply reservoirs 175, 112, 114, 116 and a waste receptacle 155. As illustrated, a yellow binder supply reservoir 112 is coupled to a yellow-designated printhead 145B, a magenta binder supply reservoir 114 is coupled to a magenta-designated printhead 145C, and a cyan binder supply reservoir 116 is coupled to a cyan-designated printhead 145D. Note that the clear binder supply reservoir 175 is coupled to a clear-designated printhead 145A and also to each of the color-designated printheads 145B, 145C, 145D. All printheads 145A-145D are also coupled to the waste receptacle 155. Further details are described below.

FIG. 11B shows the binder liquid supply apparatus for printhead 145A of FIG. 11A, which is designated to print clear (colorless) binder liquid. In the usual operating mode, valve 122A is open to allow flow, and valve 128A is closed to block flow. A pump 185A draws clear binder liquid from its reservoir 175 through a filter 118A and supplies the liquid under pressure to printhead 145A through conduit 87A and valve 122A. A pressure switch 121A is configured to inhibit the action of the pump 185A whenever a preset pressure level (for example, 3 psi) has been reached. By this mechanism, the pressure of the clear binder liquid at the printhead 145A is maintained at approximately the preset pressure level.

In an alternative operating mode, the valve 128A is opened to allow flow, allowing binder liquid from the reservoir 175 to be circulated through the apparatus and returned to the waste receptacle 155. This configuration, for example allows the binder liquid in the apparatus to be refreshed periodically when the printer is idle for long intervals. In another alternative operating mode, the valve 122A is closed to block flow, for example to prevent the binder liquid in the printhead from draining back into the clear supply reservoir 175 when the printer is inactive.

FIG. 11C shows the binder liquid supply apparatus for a printhead 145B of FIG.

11A, which is designated to print yellow binder liquid. This apparatus differs from the clear binder supply apparatus shown in FIG. 11B by the addition of a valve 120B, which is configured to allow a pump 185B to draw binder liquid as required either from the clear supply reservoir 175 or from a yellow liquid reservoir 112. The other printheads
5 145C, 145D, in a manner identical to that described for the yellow printhead 145B, can be selectively supplied with either clear binder liquid or with colored binder liquid from the associated colored liquid reservoirs 114, 116.

In the apparatus described, valves 120B-120D can all be configured to supply clear binder to their respective printheads, for example to print a monochrome part at a
10 high build rate. Alternatively, each head can be supplied with a different color to allow a colored part to be printed. When a change between color mode and monochrome mode is required, the valves 128B-128D can be opened to facilitate flushing of undesired binder liquid from the color head supply apparatus into the waste receptacle 155.

15 EQUIVALENTS

While the method and apparatus for prototyping a three-dimensional object has been particularly shown and described with references to particular embodiments thereof, it will be understood by those skilled in the art that various changes in form and details may be made without departing from the spirit and scope of the invention as
20 defined by the appended claims. These and all other equivalents are intended to be encompassed by the following claims.